## Form C

## **Information Needed to Declare Exemption**

## National Emission Standards for Hazardous Air Pollutants Received **Glass Manufacturing Area Sources**

40 CFR part 63 subpart SSSSS

JUL 24 2008

(http://www.epa.gov/ttn/atw/area/fr26de07.pdf)

Office Of Air, Waste

1. Business Name: <u>BULLSEYE</u> C	FLASS (	COMPAN	/ And Toxics	
2. Owner/Operator Name: <i>ERIC E</i> .	DURRIN	v		
3. Mailing Address: 3722 SE 2	157 AVE.	PORTLAND	OR 97202	
4. E-mail Address: <u>ERICDURRIN</u>	BULLSEY	EGLASS.C	COM	
5. Address (physical location) of Source: 37	'22 <i>SE</i>	21ST AVE	PORTLAND, OR 9720Z	
6. Primary SIC and NAICS codes: 32	11	3272	2/1	
7. Glass products manufactured: <u>COLORE</u>	ED ART	GLASS	5	
8. Do you use a continuous furnace?Yo	<del></del>			
9. Amount of glass produced: 2,500				
10. Do you add any of the following compound	is to your furna	ace charge*:		
Arsenic X Yes No Cadm				
Lead <u>×</u> Yes No Mang	anese 🗡 Ye	sNo_ N	lickel <u>×</u> Yes No	
*Note that these metals are typically found in g	plass formulation	on additives; o	ontact your supplier if you're unsu	ле.
11. Although I am not currently subject to the 0	Glass Manufac	ture's NESHA	P, I will keep records of furnace t	ypes,
glass production, and metal HAP compounds	used in furnac	e charges. 🗴	Yes No	
<ol> <li>Certification         I certify that, based on information and bel information in this report and the supporting     </li> </ol>				
Print the name of the "Responsible Official	*" for the faci	lity:		
ERIC E. DURRIN  Name of Responsible Official	CON	UTROLLET	503-232-888 Phone Number	37
Name of Responsible Official	Tit	le	Phone Number	
<ul> <li>The owner of the facility</li> <li>The plant engineer or supervision</li> <li>A government official if the factorist government</li> <li>A ranking military officer if the</li> </ul>	sor cility is owned	by the Federa		8
Signature of "Responsible Official"			Date	

Keep a copy of this form for your records.

Mail the original to:

Region 10 Office of the EPA Director, Office of Air, Waste and Toxics 1200 6<sup>th</sup> Ave., Suite 900, OAQ-107 Seattle, WA 98101

Mail or fax a copy to:

Department of Environmental Quality Attn: Jerry Ebersole 811 SW Sixth Ave Portland, OR 97204

Fax: 503-229-5675

the configuration of the configuration of the property of the Celved

24 2008

And Toxics Office Of Air, Waste

A TO BAR MAOS GARACTO DO DE 

ander of his Till for

ege armakrigingi Kitaliji Taro Awan en or ils di**en**ie energiese in de arthé

Companies (Colors Colors Colors Colors (Colors Colors (Colors Colors Col မြန်များသည်။ အခြောင်း အခြောင်းများသည်။ အခြောင်းများသည် မြောက်သည်။ အခြောင်းများသည်။ အခြောင်းများသည်။ မြောက်သည်။

TANK TO THE TANK TO WANT

Compression of the first of the party of the

us reger perceptuare en a morris proceptance per a subject de program to document in a competitiva en competit

the interpretational metal in the interpretational production of the production of t ा पूर्वात हो है <mark>। अ</mark>ग्नु के **राज्यक्ता**र के के दिन के तह है महत्त्व का कार्यक्र के किए कि सम्मान की कार्यक्र के कि कि सम्मान की कार्यक्र के कि

့္က ကမၻာ့ ၁၈ (၁၂၁) မည်းတွင္းမက္က မူခ်ာ အခြာမတုပ္သည့္သည္ခ်ားကရတာကတင္းေရးမွာပဲ မတိုင္မ်ား ေအမရို စစ္ပုပ်မႈ နွစ္ျပ ्रेटरेट्ट है। हुन हुन र नाम महाबार एक संज के हुन हो क्रिकेट पाल र मध्य हो के के महाबाद के मान के महास्त्रीका क

2017年6月1日 11日本 gus las ser la militar de de la periorita de deservação do procesor de la composição de la composição de la co

्र विकास के जिल्ला है है है । असे अक्षेत्र के स्थाप के महिल्ला के स्थाप के किस के स्थाप के स्थाप के स्थाप की 

ទីសក្សាស៊ីសម្រាប់ នាម នេះស្ថាមប្រាស្ត្រីស្ថិត្រសាប់ (សេសក្នុស្ត្រី)

इत्तरे प्रदर्भते सुरूष्ट्रा कुन्ने कुन्ने पर विद्वार सामानुष्ट्र

्रात्ति विकास १५० व्यक्तिसम्बद्धाः १५४ सन्दर्भवे सम्बद्धाः १५५ व्यक्तिसम्बद्धाः

in programme to the second of the second of

Thougas 1985 in

प्रतिकृति । स्थापित स्थापित । स्थापित ।

(Light from the state of the first and for each 25 in heart from ) ५० Class मध्य हड कर्किको १९४४ छ।

नुसूच्याक का**द्या**त्रस् मञ्जूताक्ष्यां में देवण त्राव र प्रातान